

**NOTICE TO OUR CUSTOMERS:**  
**WHEN REPLACING THE KILN SITTER® SWITCH BLOCK ASSEMBLY,**  
**BE SURE TO CHECK THE CONNECTIONS FOR SIGNS OF**  
**CORROSION. IF THE PLUNGER BUTTON HAS MELTED, THE**  
**CONTACTS ARE BLUED AND/OR THE WIRES ARE BRITTLE OR**  
**BURNED, IT HAS BEEN CAUSED FROM THE HEAT GENERATED BY**  
**THE CONNECTIONS ON THE BACKSIDE OF THE SWITCH.**  
**BE SURE TO CHECK AND REPLACE THE SCREWS, WIRES AND**  
**LUGS IF THERE IS ANY QUESTION AS TO THEIR CONDITION.**

**W.P.DAWSON, INC. 399 THOR PLACE BREA-CA-92821**  
**714.529.2813 FAX 714.529.3254**