

NOTICE TO OUR CUSTOMERS:
WHEN REPLACING THE KILN SITTER® SWITCH BLOCK ASSEMBLY,
BE SURE TO CHECK THE CONNECTIONS FOR SIGNS OF
CORROSION. IF THE PLUNGER BUTTON HAS MELTED, THE
CONTACTS ARE BLUED AND/OR THE WIRES ARE BRITTLE OR
BURNED, IT HAS BEEN CAUSED FROM THE HEAT GENERATED BY
THE CONNECTIONS ON THE BACKSIDE OF THE SWITCH.
BE SURE TO CHECK AND REPLACE THE SCREWS, WIRES AND
LUGS IF THERE IS ANY QUESTION AS TO THEIR CONDITION.

W.P.DAWSON, INC. 399 THOR PLACE BREA-CA-92821
714.529.2813 FAX 714.529.3254